SEGRE

Declassification Review by NGA/DoD

OUT55526

SECRET 221945Z

1965 APR 22 20 36 Z

- 1. CAMERA B 101 WAS USED IN MISSION 8012 FLOWN ON 20 APRIL 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.
 - 2. GRIGINAL NEGATIVE:

ED & ON FRAME 1224.

- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: THE POSITION INDICATOR LAMP WAS INOPERATIVE

 COPIES RECEIVED

 THROUGHOUT THE MISSION. THERE IS A CONTINUOUS MINUS DENSITY

 STREAK 6.7" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM

 THROUGHOUT THE MISSION. THERE ARE MANUFACTURING SPLICES ON FRAMES

 196, 1356 AND 2516. THERE ARE HEAT SPLICES ON FRAMES 353 AND

 1468.
- C. SL SIDE: THERE IS A ROW OF PLUS DENSITY SPOTS NEAR THE IN BOARD EDGE OF THE FILM THROUGHOUT THE MISSION. STATIC DISCHARGES OCCUR INTERMITTENTLY AT THE INBOARD EDGE OF THE FILM.

 A CONTINUOUS PLUS DENSITY STREAK, 2.16" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM, IS PRESENT ON FRAMES 23 THROUGH

 484. HEAT SPLICES ARE MADE IN FRAMES 484, 1624 AND BETWEEN FRAMES 1933/1934. THERE ARE MIN OR CRIMPS AND PLUS DENSITY STREAKS ASSOCIATED WITH THE SPLICE IN FRAME 484. THE MANUFACTURER'S SPLICE MADE IN FRAME 1227 CAUSED A SLIGHT DENSITY BAND, EDGE TO
- D. BOTH SIDES: STATIC DISCHARGES OCCUR INTERMITTENTLY
 AT THE OUTBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. SLIGHT
 FOGGING IS PRESENT ALONG THE INBOARD EDGE OF THE FILM THROUGHOUT.
 A WAVERING PLUS DENSITY STREAK OCCURS INTERMITTENTLY AND WITHIN

23 APR **1965**

25X1

- 1.5" OF THE INBOARD EDGE OF THE FILM. A SLIGHT FLARE IS PRESENT ON EACH FRAME NEAR THE DATA CHAMBER. FRAMES ARE TITLED CONSECUTIVELY FROM 8081 THROUGH 2845.
- E. THERE ARE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS.
 - 3. POSITIVE:
 - A PI SUITABILITY IS GOOD.
 - B PRINTING AND PROCESSING ARE GOOD.
- C CLOUDS OBSCURE OR DEGRADE LESS THAN 5 PERCENT OF THE MISSION SECRET

-- END OF MESSAGE --